Change Order Outline:

•	25	Window Credit 1509 Schwab	(\$4,258.81)
•	26	Duct Work Credit 1509 Schwab	(12,511.68)
•	28	Mini Split in 1509 Schwab	\$12,419.69
•	29	Light Credit 1509 Schwab	(1,408.00)
•	32	Excavate Mechanical Bays	\$15,000.00
•	33	**Correction** Excavation	\$1,497.90
•	47	Rollup Door Threshold	\$1,540.98
•	51	Subsurface Issues with Solar Structure	\$5,122.88
•	56	Connect Gas Line to Office 304	\$566.36
•	57	Privacy Fencing for Yard	\$12,495.52
•	58	Solar Structure Concrete Testing	\$1,032.34
•	59	Roof Repairs and Insulation	\$28,618.00
•	60	Mechanic Bay Exhaust and Heaters	\$9,753.68
•	61	Stair Handrail	\$4,403.00
٠	62	Insullate Shop Walls 1820 Bidwell Bays	\$28,610.26
٠	63	Blue Paint in Mechanical Bay	\$813.05
٠	64	Base Testing for Paving	\$299.40
٠	65	Mezzanine Door	\$2,548.60
٠	66	Drywall Framing	\$6,865.09
٠	67	Security Cameras	\$17,160.38
٠	68	Solar Irrigation Controller	\$2,849.99
•	69	Hose Faucet	\$535.61
•	70	Ceiling Insulation in 1820 Bidwell	\$62,347.00
•	71	Copy Machine Power	\$2,229.89
•	72	Plotter Machine Power	\$2,484.11
•	73	Mini-Split in Storage Area	\$12,589.22
•	74	Parking Bumpers	\$2,787.60
•	75	Data Cables for Plotter	\$738.04
•	76	Baby Changing Station	\$2,127.82
•	77	Garbage Disposal	\$1,568.03
•	77.1	Power to Garbage Disposal	\$2,671.45
•	78	Storage Room Flooring and Paint	\$14,962.18
•	79	Intercom to Flood Suite	\$11,783.95